CERTIFICATE OF PUBLICATION

This is to certify that this official notice appeared at www.link2build.ca on

August 19, 2026

Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

Where the Premises is Situated
377 Riverside Dr East, Windsor, ON, Canada N9A 7H7

Where the Premises is Located
Windsor, Ontario, Canada

This is to certify that the contract for the following improvement
Enwave Windsor Plant - North Block Plant Heating Plant Upgrades - Phase 2

To the above premises was substantially performed on
6/11/2026

Date Certificate Signed
8/14/2026

Name of Owner
Enwave Energy Corporation

Mailing Address of Owner
16 York St 22 floor, Toronto, ON M5J 0E6

Name of Contractor
Vollmer Inc.

Mailing Address of Contractor
3822 Sandwich St, Windsor, ON N9C 1C1

Name of Payment Certifier
MCW Consultants Ltd

Mailing Address of Payment Certifier
207 Queen's Quay West, Suite 615, Toronto, ON M5J 1A7

Type
A. Identification of premises for preservation of liens

Description
North Block:
Firstly: PIN 01169-0505 (LT), PCL 9−2 SEC WINDSOR−106; PT LTS 9 TO 12, 21 PL 106, LTS 22 TO 24 PL 106, LT 20 PL 122, PT LTS 1, 2, 18, 19, 21, 22 & 23 PL 122, PT LT 2 (S/S SANDWICH ST) & PT LT 2 (N/S STUART ST) PL 123 PT 3 12R13958, T/W A TEMPORARY EASEMENT & RIGHT−OF−WAY TO ENTER OVER, ALONG & UPON PT LTS 9 TO 12, 21 PL 106, PT LTS 1 & 2 PL 122 & PT LT 2 (S/S SANDWICH ST) PL 123 PT 2 12R13958 AS IN LT185727; WINDSOR
Secondly: PIN 01169−0497 (LT), LT 12 PL 122 WINDSOR; LT 13 PL 122 WINDSOR; LT 14 PL 122 WINDSOR; LT 15 PL 122 WINDSOR; LT 16 PL 122 WINDSOR; LT 17 PL 122 WINDSOR; LT 30 PL 122 WINDSOR; LT 31 PL 122 WINDSOR; LT 32 PL 122 WINDSOR; LT 33 PL 122 WINDSOR; LT 34 PL 122 WINDSOR; LT 35 PL 122 WINDSOR; LT 36 PL 122 WINDSOR; LT 37 S/S STUAR
WINDSOR;
WINDSOR;
WINDSOR;
WINDSOR;
PT LT 8 PL
122 WINDSOR; PT LT 18 PL 122 WINDSOR; PT LT 19 PL 122 WINDSOR; PT LT 21 PL 122

View your publication online at: https://certificates.link2build.ca/
25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7547 / info@link2build.ca

WINDSOR; PT LT 22 PL 122 WINDSOR; PT LT 23 PL 122 WINDSOR; PT LT 2 N/S STUART ST PL 123 WINDSOR; PT LT 5 S/S SANDWICH ST PL 123 WINDSOR; PT LT 1 BLK 3 PL 126 WINDSOR; PT LT 2 BLK 3 PL 126 WINDSOR; PT LT 3 BLK 3 PL 126 WINDSOR; PT LT 4 BLK 3 PL 126 WINDSOR; PT LT 5 BLK 3 PL 126 WINDSOR; PT LT 6 BLK 3 PL 126 WINDSOR; PT LT 1 BLK 4 PL 126 WINDSOR; PT WILLIAM ST PL 106 WINDSOR AKA PITT ST CLOSED BY R1307647; PT STUART ST PL 122 WINDSOR AKA PITT ST CLOSED BY R1307647; PT MERCER ST PL 122 WINDSOR CLOSED BY R1307647; PT ALLEY PL 122 WINDSOR CLOSED BY R1307647; PT STUART ST PL 126 WINDSOR AKA PITT ST CLOSED BY R1307647; PT ALLEY PL 126 WINDSOR CLOSED BY R1307647; PT 4, 12R13958; T/W R1313548; WINDSOR

Thirdly: PIN 01169-0504 (LT), PCL 25−2 SEC WINDSOR−106; PT LTS 25 TO 28, 37 TO 40 PL 106, LTS 24 TO 29, 37 TO 39, PT OF PITT ST E (FORMERLY STUART ST AS CLOSED BY BYLAW R1230673), PT OF PITT ST E (AS CLOSED BY BYLAW 19 REG AS 19), PT ALLEY CLOSED BY BYLAW R561143, PT ALLEY CLOSED BY BYLAW R1148008 PL 122, LT 4 S/S OF PITT ST E (FORMERLY STUART ST), LTS 3 & 4 N/S CHATHAM ST E (FORMERLY ARTHUR ST) PL 123 PTS 6 & 7 12R13958, T/W PT LTS 28, 37 TO 40 PL 106, T/W PTS 8 & 9 12R13958 AS IN LT185727, S/T R1148008 & R1157368; WINDSOR