

# **CERTIFICATE OF PUBLICATION**

This is to certify that this official notice appeared at www.link2build.ca on

October 20, 2025

## Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

#### Where the Premises is Situated

8591 Riverside Drive East, Windsor, ON

#### Where the Premises is Located

City of Windsor

## This is to certify that the contract for the following improvement

Bayview Towers - East Wall Brick Repair

## To the above premises was substantially performed on

10/17/2025

#### **Date Certificate Signed**

10/17/2025

#### Name of Owner

Essex Condominium Corporation #22

#### Mailing Address of Owner

8591 Riverside Drive East, Windsor, ON

#### Name of Contractor

Weathertech Restoration Services Inc.

## **Mailing Address of Contractor**

1054 Shaw Road, Dorchester, ON N0L 1G4

#### Name of Payment Certifier

D.C. McCloskey Engineering Ltd.

## **Mailing Address of Payment Certifier**

5745 Wyandotte Street East, Suite 200, Windsor, ON, N8S 1M6

#### Type

A. Identification of premises for preservation of liens

#### Description

Bayview Towers - 8591 Riverside Drive East, Windsor, ON

View your publication online at: <a href="https://certificates.link2build.ca/">https://certificates.link2build.ca/</a>

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / info@link2build.ca













