

# **CERTIFICATE OF PUBLICATION**

This is to certify that this official notice appeared at www.link2build.ca on

September 26, 2023

## Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

### Where the Premises is Situated

Ontario, Canada

#### Where the Premises is Located

41-77 Enroutes St., 50 & 60 Belleville St., 3-39 Philpott Gardens, Toronto

## This is to certify that the contract for the following improvement

Balcony Repairs - Phase 3 (41 to 59 Enroutes St.)

## To the above premises was substantially performed on

9/21/2023

### **Date Certificate Signed**

9/22/2023

## Name of Owner

Toronto Standard Condominium Corporation No.2089

#### Mailing Address of Owner

c/o Eastway Management Inc. 250 Water Street, Suite 202 Whitby, Ontario, L1N0G5

## Name of Contractor

Vidan Roofing & Contracting Inc.

## **Mailing Address of Contractor**

170 Roxton Rd, Toronto Ontario M6J 2Y5

## Name of Payment Certifier

Edison Engineers Inc.

## **Mailing Address of Payment Certifier**

105-6 Shields Court Markham, Ontario L3R 4S1

#### Type

A. Identification of premises for preservation of liens

### Description

Block 51, Plan 66M-2414, designed as Part 3 and 6 on Plan 66R-24294, Part of Musgrave Street designated as Part 1 on Plan 66R-24470 and Part of Lot 1, Concession 1, From The Bay designated as Part 2 on Plan 66R-24470, City of Toronto

View your publication online at: https://certificates.link2build.ca/

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / info@link2build.ca













