

CERTIFICATE OF PUBLICATION

This is to certify that this official notice appeared at www.link2build.ca on

September 28, 2022

Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

Where the Premises is Situated

City of London

Where the Premises is Located

160 Emery Street West, London, Ontario, N6J 3W3

This is to certify that the contract for the following improvement

Balcony Railing Replacement, Waterproofing and Localized Concrete Repairs

To the above premises was substantially performed on

9/23/2022

Date Certificate Signed

9/27/2022

Name of Owner

Mantler Management Limited

Mailing Address of Owner

5667 Highway 7, Markham, Ontario, M3P 1B3

Name of Contractor

WeatherTech Restoration Services Inc.

Mailing Address of Contractor

1054 Shaw Road, Dorchester, Ontario, N0L 1G4

Name of Payment Certifier

RDQ Engineering Inc.

Mailing Address of Payment Certifier

2399 Cawthra Road, Unit 201, Mississauga, Ontario, L5A 2W9

Type

A. Identification of premises for preservation of liens

Description

Mantler Management Limited;
160 Emery Street West, London, Ontario, N6J 3W3

View your publication online at: <https://certificates.link2build.ca/>

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / info@link2build.ca

