

# **CERTIFICATE OF PUBLICATION**

This is to certify that this official notice appeared at www.link2build.ca on

November 8, 2022

## Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

### Where the Premises is Situated

Municipality of South Dundas

#### Where the Premises is Located

3005 to 3990 Taylor Road, Municipality of South Dundas (Taylor Bridge and Approaches)

## This is to certify that the contract for the following improvement

Contract No. TS22-12 - Taylor Bridge Replacement

## To the above premises was substantially performed on

11/7/2022

### **Date Certificate Signed**

11/7/2022

### Name of Owner

Municipality of South Dundas

## Mailing Address of Owner

34 Ottawa Street, PO Box 740, Morrisburg, ON, K0C1X0

## Name of Contractor

**DW Building Restoration** 

## **Mailing Address of Contractor**

2338 Riley Ave, Ottawa, ON, K2C 1J9

#### Name of Payment Certifier

Keystone Bridge Management Corp.

## **Mailing Address of Payment Certifier**

714-B Front Road, Kingston, ON K7M 4L5

#### **Type**

B. Office to which claim for lien must be given to preserve lien

### Description

Municipality of South Dundas, 34 Ottawa Street, PO Box 740, Morrisburg, ON, K0C 1X0

View your publication online at: <a href="https://certificates.link2build.ca/">https://certificates.link2build.ca/</a>

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / info@link2build.ca













