

# **CERTIFICATE OF PUBLICATION**

This is to certify that this official notice appeared at www.link2build.ca on

**December 13, 2023** 

# Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

#### Where the Premises is Situated

Sandy Lake First Nation, Sandy Lake, Ontario

#### Where the Premises is Located

Sandy Lake First Nation, Sandy Lake, Ontario

## This is to certify that the contract for the following improvement

Sandy Lake First Nation Hydrant Replacement/Repair and Associated Works

# To the above premises was substantially performed on

11/9/2023

#### **Date Certificate Signed**

11/28/2023

## Name of Owner

Sandy Lake First Nation

#### Mailing Address of Owner

PO Box 12, Sandy Lake, ON P0V 1V0

### Name of Contractor

Penn-co Construction Canada (2003) Ltd.

# **Mailing Address of Contractor**

PO Box 60, 25 Penner Drive, Blumenort, MB R0A 0C0

#### Name of Payment Certifier

Neegan Burnside Ltd.

## **Mailing Address of Payment Certifier**

307 Commerce Drive, Winnipeg, MB R3P 1B3

#### Type

B. Office to which claim for lien must be given to preserve lien

#### Description

Colliers Project Leaders 715 Hewitson St Suite 2002 Thunder Bay, ON P7B 6B5

View your publication online at: <a href="https://certificates.link2build.ca/">https://certificates.link2build.ca/</a>

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / info@link2build.ca













