

## CERTIFICATE OF PUBLICATION

This is to certify that this official notice appeared at [www.link2build.ca](http://www.link2build.ca) on

**February 28, 2022**

### Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

**Where the Premises is Situated**

Mississauga Ontario

**Where the Premises is Located**

3610 Dixie Road

**This is to certify that the contract for the following improvement**

Remove 99 trees, cut stumps as close to soil grade as possible, clean up all brush and wood and remove from site

**To the above premises was substantially performed on**

8/26/2019

**Date Certificate Signed**

1/4/2022

**Name of Owner**

Killam Apartment Subsidiary Limited Partnership

**Mailing Address of Owner**

3700 Kempt Road, Suite 100 Halifax, NS B3K 4X8

**Name of Contractor**

Maple Hill Tree Services

**Mailing Address of Contractor**

1220 Heritage Road, Burlington, ON L7L 4X9

**Name of Payment Certifier**

ABA Architects

**Mailing Address of Payment Certifier**

101 Randall Drive, Unit B, Waterloo, ON N2V 1C5

**Type**

A. Identification of premises for preservation of liens

**Description**

3610 Dixie Road, Mississauga, ON L4Y 3V9

View your publication online at: <https://certificates.link2build.ca/>

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / [info@link2build.ca](mailto:info@link2build.ca)

