

## CERTIFICATE OF PUBLICATION

This is to certify that this official notice appeared at [www.link2build.ca](http://www.link2build.ca) on

**August 13, 2024**

### Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

**Where the Premises is Situated**

1030 Coronation Dr., London

**Where the Premises is Located**

ON, CA

**This is to certify that the contract for the following improvement**

Recoating the Building Walls and Localized Sealant/Concrete Repairs

**To the above premises was substantially performed on**

8/1/2024

**Date Certificate Signed**

8/13/2024

**Name of Owner**

Middlesex Standard Condominium Corporation No. 759

**Mailing Address of Owner**

c/o Culture Property Management Inc., 1585 Stn Main, Woodstock, ON N4S 0A7

**Name of Contractor**

WeatherTech Restoration Services Inc.

**Mailing Address of Contractor**

1054 Shaw Road, Dorchester ON N0L 1G4

**Name of Payment Certifier**

Edison Engineers Inc.

**Mailing Address of Payment Certifier**

Unit 124-4056 Meadowbrook, London ON N6E 1A2

**Type**

A. Identification of premises for preservation of liens

**Description**

1030 Coronation Drive, London (part of Lot 24, Concession 3, Plan 33R-17851)

View your publication online at: <https://certificates.link2build.ca/>

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / [info@link2build.ca](mailto:info@link2build.ca)

