

# **CERTIFICATE OF PUBLICATION**

This is to certify that this official notice appeared at www.link2build.ca on

October 2, 2020

# Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

# Where the Premises is Situated

Mallorytown

#### Where the Premises is Located

70 County Road 5 South, Mallorytown, Ontario

# This is to certify that the contract for the following improvement

Cladding Repairs and Building Restoration - 2020

# To the above premises was substantially performed on

9/30/2020

#### **Date Certificate Signed**

10/1/2020

## Name of Owner

1808841 Ontario LTD

#### **Mailing Address of Owner**

70 County Rd 5 South, Mallorytown, Ontario K0E 1R0

# Name of Contractor

Dolyn Construction Ltd.

# **Mailing Address of Contractor**

888 Lady Ellen Place, Ottawa, Ontario K1Z 5L5

#### Name of Payment Certifier

EXP Services Inc.

## **Mailing Address of Payment Certifier**

2650 Queensview Drive, Unit 100, Ottawa, Ontario K2B 8H6

#### Type

A. Identification of premises for preservation of liens

#### Description

70 County Rd 5 South, Mallorytown, Ontario K0E 1R0

View your publication online at: <a href="https://certificates.link2build.ca/">https://certificates.link2build.ca/</a>

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / info@link2build.ca













