

# **CERTIFICATE OF PUBLICATION**

This is to certify that this official notice appeared at www.link2build.ca on

May 10, 2023

# Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

#### Where the Premises is Situated

Toronto, Ontario

#### Where the Premises is Located

40 Tyndall Avenue, Toronto, ON M6K 2E4

### This is to certify that the contract for the following improvement

Mechanical System Retrofits: Parking Garage Ventiliation & DCW Service Upgrades

### To the above premises was substantially performed on

5/8/2023

#### **Date Certificate Signed**

5/8/2023

### Name of Owner

DMS Property Management Ltd.

#### Mailing Address of Owner

4800 Dufferin Street., North York, ON M3H 5S9

## Name of Contractor

Kelson Service Inc.

# **Mailing Address of Contractor**

2 Bales Drive West, Sharon, ON L0G 1V0

# Name of Payment Certifier

Trinity Engineering & Consulting Inc.

### **Mailing Address of Payment Certifier**

247 North Service Road W., Suite 301, Oakville, ON L6M 3E6

#### Type

A. Identification of premises for preservation of liens

#### Description

40 Tyndall Avenue, Toronto, ON M6K 2E4

View your publication online at: <a href="https://certificates.link2build.ca/">https://certificates.link2build.ca/</a>

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / info@link2build.ca













