

# **CERTIFICATE OF PUBLICATION**

This is to certify that this official notice appeared at www.link2build.ca on

**September 11, 2023** 

## Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

#### Where the Premises is Situated

Ottawa, Ontario

#### Where the Premises is Located

179 Metcalfe Street, Ottawa. Ontario, K2P 2L2

### This is to certify that the contract for the following improvement

20136 - OCSCC 961 - Riser and Insulation Repairs - Phase 2

#### To the above premises was substantially performed on 9/7/2023

#### **Date Certificate Signed**

9/11/2023

#### Name of Owner

Ottawa Carleton Standard Condominium Corporation No. 961

#### Mailing Address of Owner

c/o CMG, 434 Queen Street, Ottawa, Ontario K1R 7V7

#### Name of Contractor

BGC Construction & Restoration Ltd.

### **Mailing Address of Contractor**

860 Boyd Avenue, Ottawa, Ontario, K2A 2E1

### Name of Payment Certifier

Keller Engineering

### **Mailing Address of Payment Certifier**

500-885 Meadowlands Drive, Ottawa, Ontario, K2P 2L2

A. Identification of premises for preservation of liens

#### Description

179 Metcalfe Street, Ottawa, Ontario, K2P 2L2

View your publication online at: <a href="https://certificates.link2build.ca/">https://certificates.link2build.ca/</a>

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / info@link2build.ca













