

# **CERTIFICATE OF PUBLICATION**

This is to certify that this official notice appeared at www.link2build.ca on

October 27, 2023

# Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

#### Where the Premises is Situated

City of Ottawa

#### Where the Premises is Located

Longfields Drive, Lindenshade Drive and Sue Holloway Drive, Ottawa ON

### This is to certify that the contract for the following improvement

Entrance Stair Repairs at OCSCC 918

## To the above premises was substantially performed on

10/23/2023

#### **Date Certificate Signed**

10/27/2023

#### Name of Owner

Ottawa-Carleton Standard Condominium Corporation No. 918 c/o Condominium Management Group

#### **Mailing Address of Owner**

434 Queen Street Ottawa, Ontario, K1R 7V7

### **Name of Contractor**

Bassi Construction LP

### **Mailing Address of Contractor**

2575 Del Zotto Avenue Ottawa, Ontario, K1T 3V6

#### Name of Payment Certifier

Paterson Group Inc.

# Mailing Address of Payment Certifier

9 Auriga Drive Ottawa, Ontario, K2E 7T9

#### Type

A. Identification of premises for preservation of liens

#### Description

Longfields Dr., Lindenshade Dr. & Sue Holloway Dr. Ottawa, Ontario, K2J 5R4

View your publication online at: <a href="https://certificates.link2build.ca/">https://certificates.link2build.ca/</a>

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / info@link2build.ca













