



CERTIFICATE OF PUBLICATION

This is to certify that this official notice appeared at www.link2build.ca on

October 26, 2023

Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

Where the Premises is Situated

Ottawa, ON

Where the Premises is Located

555 Brittany Dr., Ottawa, ON

This is to certify that the contract for the following improvement

Balcony Repairs and Sealant Replacement

To the above premises was substantially performed on

10/13/2023

Date Certificate Signed

10/19/2023

Name of Owner

Carleton Condominium Corporation No. 105

Mailing Address of Owner

555 Brittany Drive, Ottawa, ON K1K 4C5

Name of Contractor

Jonas Building Restoration Ltd.

Mailing Address of Contractor

3717 St. Joseph Blvd., Orleans, ON K4A 0Z7

Name of Payment Certifier

WSP Canada Inc.

Mailing Address of Payment Certifier

2611 Queensview Drive, Suite 300, Ottawa, ON K2B 8K2

Type

A. Identification of premises for preservation of liens

Description

555 Brittany Drive, Ottawa, ON K1K 4C5

View your publication online at: <https://certificates.link2build.ca/>

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / info@link2build.ca

