

CERTIFICATE OF PUBLICATION

This is to certify that this official notice appeared at www.link2build.ca on

October 14, 2021

Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

Where the Premises is Situated

Toronto, Ontario

Where the Premises is Located

2682 Keele Street, Toronto, ON, M3M 3G5

This is to certify that the contract for the following improvement

Repair to floor cracks and block walls in penthouse of the OPP detachment (1079921-OPP Structural Repairs (272620))

To the above premises was substantially performed on

10/14/2021

Date Certificate Signed

10/14/2021

Name of Owner

Infrastructure Ontario

Mailing Address of Owner

1 Dundas St W, Suite 2000, Toronto, ON, M5G 2L5

Name of Contractor

Rodas McKnight Constructors INC

Mailing Address of Contractor

2500, 88 Queens Quay W, Toronto, ON, M5J 0B8

Name of Payment Certifier

Milman & Associates Limited

Mailing Address of Payment Certifier

225, 1750 Steeles Ave W, Vaughan, ON, L4K 2L7

Type

B. Office to which claim for lien must be given to preserve lien

Description

President & CEO, Infrastructure Ontario, 1 Dundas St W, Suite 2000, Toronto, ON, M5G 2L5

View your publication online at: <https://certificates.link2build.ca/>

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / info@link2build.ca

