

# **CERTIFICATE OF PUBLICATION**

This is to certify that this official notice appeared at www.link2build.ca on

October 21, 2025

## Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

#### Where the Premises is Situated

Toronto

### Where the Premises is Located

349 St Clair Avenue West, Toronto, Ontario, M5P 1N3

### This is to certify that the contract for the following improvement

**HVAC** Replacement

## To the above premises was substantially performed on

8/15/2025

## **Date Certificate Signed**

9/25/2025

#### Name of Owner

York Condominium Corporation No. 310

#### Mailing Address of Owner

349 St Clair Avenue West, Toronto, Ontario, M5P 1N3

## Name of Contractor

Kelson Service Inc.

## **Mailing Address of Contractor**

2 Bales Drive West, Sharon, Ontario, L0G 1V0

## Name of Payment Certifier

Trace Consulting Group Ltd.

### **Mailing Address of Payment Certifier**

240 Chrislea Road, Vaughan, ON, L4L 8V1

#### Type

A. Identification of premises for preservation of liens

#### Description

York Condominium Corporation No.310 - 349 St. Clair Avenue West, Toronto, Ontario, M5P 1N3

View your publication online at: <a href="https://certificates.link2build.ca/">https://certificates.link2build.ca/</a>

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / info@link2build.ca













