

# **CERTIFICATE OF PUBLICATION**

This is to certify that this official notice appeared at www.link2build.ca on

June 6, 2024

# Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

### Where the Premises is Situated

130 Neptune Drive, North York, Ontario M6A 2Y4

#### Where the Premises is Located

City of Toronto

# This is to certify that the contract for the following improvement

Cooling Tower and MUA Units Replacement & Chiller Overhaul

# To the above premises was substantially performed on

6/5/2024

#### **Date Certificate Signed**

6/5/2024

#### Name of Owner

York Condominium Corporation No.67

#### Mailing Address of Owner

130 Neptune Drive, North York, Ontario, M6A 2Y4

### Name of Contractor

Kelson Service Inc.

## **Mailing Address of Contractor**

2 Bales Drive West, Sharon, Ontario, L0G 1V0

# Name of Payment Certifier

Rohini Sri Satgunarajah

### **Mailing Address of Payment Certifier**

240 Chrislea Road, Suite 105 - Vaughan, Ontario, L4L 8V1

#### Type

B. Office to which claim for lien must be given to preserve lien

#### Description

130 Neptune Dr - Management Office

View your publication online at: <a href="https://certificates.link2build.ca/">https://certificates.link2build.ca/</a>

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / info@link2build.ca













