

# **CERTIFICATE OF PUBLICATION**

This is to certify that this official notice appeared at www.link2build.ca on

February 13, 2025

# Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

### Where the Premises is Situated

138 Union Street, Kingston

#### Where the Premises is Located

City of Kingston

## This is to certify that the contract for the following improvement

Sutherland Hall Flood repair

## To the above premises was substantially performed on

12/19/2024

### **Date Certificate Signed**

2/10/2025

#### Name of Owner

Queen's University Physical Plant Services

## **Mailing Address of Owner**

355 King St. W 2nd Floor Kingston, ON K7L 3N6

#### Name of Contractor

David J. Cupido Construction Ltd.

### **Mailing Address of Contractor**

4 - 620 Cataraqui Woods Drive, Kingston, ON K7P 1T8

#### Name of Payment Certifier

Colbourne & Kembel, Architects Inc.

#### **Mailing Address of Payment Certifier**

739D Arlington Park Place, Kingston, ON K7M 8M8

#### Type

A. Identification of premises for preservation of liens

#### Description

Plan A18 Lots 7 to 10 12 13; 16 and 17 Pt Lot 11 Pt; Closed Alfred St.

View your publication online at: <a href="https://certificates.link2build.ca/">https://certificates.link2build.ca/</a>

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / info@link2build.ca













