Link2Build ONTARIO

CERTIFICATE OF PUBLICATION

This is to certify that this official notice appeared at www.link2build.ca on

September 17, 2026

Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

Where the Premises is Situated
Lively, Ontario

Where the Premises is Located
1039 Creighton Mine Road, Greater Sudbury, Ontario P3Y 1N2

This is to certify that the contract for the following improvement
Repairs to Sand Tank #1

To the above premises was substantially performed on
9/16/2026

Date Certificate Signed
9/16/2026

Name of Owner
Vale Canada Limited

Mailing Address of Owner
200 Bay Street, Royal Bank Plaza, South Tower, Toronto, Ontario M5J 2K2

Name of Contractor
Lopes Limited

Mailing Address of Contractor
84 Smelter Road, Coniston, Ontario P0M 1M0

Name of Payment Certifier
N/A

Mailing Address of Payment Certifier
N/A

Type
A. Identification of premises for preservation of liens

Description
Creighton Mine 46°27′50″N 81°10′29″W