



## CERTIFICATE OF PUBLICATION

This is to certify that this official notice appeared at [www.link2build.ca](http://www.link2build.ca) on

**May 10, 2023**

### Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

**Where the Premises is Situated**

Toronto, Ontario

**Where the Premises is Located**

87 Jameson Avenue, Toronto, ON M6K 2W8

**This is to certify that the contract for the following improvement**

Mechanical System Retrofits: Parking Garage Ventilation & DCW Service Upgrades

**To the above premises was substantially performed on**

5/8/2023

**Date Certificate Signed**

5/8/2023

**Name of Owner**

DMS Property Management Ltd.

**Mailing Address of Owner**

4800 Dufferin St., North York, ON M3H 5S9

**Name of Contractor**

Kelson Service Inc.

**Mailing Address of Contractor**

2 Bales Dr. W, Sharon, ON L0G 1V0

**Name of Payment Certifier**

Trinity Engineering & Consulting Inc.

**Mailing Address of Payment Certifier**

247 North Service Road W., Suite 301, Oakville, ON L6M 3E6

**Type**

A. Identification of premises for preservation of liens

**Description**

87 Jameson Avenue, Toronto, ON M6K 2W8

View your publication online at: <https://certificates.link2build.ca/>

25 Sheldon Drive, Cambridge, ON N1R 6R8, Phone: 1-800-265-7847 / [info@link2build.ca](mailto:info@link2build.ca)

