Link2Build ONTARIO

CERTIFICATE OF PUBLICATION

This is to certify that this official notice appeared at www.link2build.ca on

June 26, 2026

Form 9 - Certificate of Substantial Performance

Certificate of Substantial Performance of the Contract Under Section 32 of the Act (Construction Act)

Where the Premises is Situated
2759 Carousel Crescent

Where the Premises is Located
Ottawa

This is to certify that the contract for the following improvement
Garbage Room Repairs

To the above premises was substantially performed on
5/21/2026

Date Certificate Signed
6/15/2026

Name of Owner
Carleton Condominium Corporation No.383 c/o Apollo CI Condo Management

Mailing Address of Owner
2759 Carousel Crescent, Ottawa, ON K1T 2N5

Name of Contractor
1881445 Ontario Inc o/a Mascon Restorations Inc

Mailing Address of Contractor
233 Russ Bradley Rd, Unit #2, Ottawa, ON K0A 1L0

Name of Payment Certifier
WSP Canada Inc.

Mailing Address of Payment Certifier
300-2611 Queensview Drive, Ottawa, ON K2B 8K2

Type
A. Identification of premises for preservation of liens

Description
2759 Carousel Crescent, Ottawa, ON K1T 2N5